



2395 West 4th Avenue Denver, CO 80223 USA Phone 303.892.0400 Toll Free 800.333.4234 Fax 303.825.5988 EMail info@BisonlP.com Web www.BisonlP.com

BOTTOM OF FASCIA BOARD MAY BE CUT ABOVE SUBSTRATE TO ALLOW WATER TO ESCAPE. FASCIA BOARD MUST FULLY CONTAIN PAVERS, AND MUST TIE BACK INTO A BUILDING WALL OR PARAPET.



WOOD FASCIA CONTAINMENT

BOTTOM OF METAL
CONTAINMENT MAY BE
BENT OR CUT ABOVE
SUBSTRATE TO ALLOW
WATER TO ESCAPE. METAL
CONTAINMENT MUST FULLY
CONTAIN PAVERS, AND
MUST TIE BACK IN TO A
BUILDING WALL OR
PARAPET.



METAL FLASHING CONTAINMENT

GENERAL NOTES: APPLY TO ALL OF THE ABOVE PRODUCTS

- 1. INSTALLATION MUST BE COMPLETED IN ACCORDANCE WITH BISON INNOVATIVE PRODUCTS SPECIFICATIONS.
- 2. DRAWINGS NOT TO SCALE.
- 3. CONTRACTOR'S NOTE: FOR PRODUCT AND COMPANY INFORMATION VISIT www.BisonIP.com

